

**New** Service being offered by IRP



"more products...  
...more solutions"

# Conveyor Spot Repairs

*Saves Money, Time & Material Loss*

This spotter offers a fast, versatile repair job that can be done on belt edges, lifting splices, holes in belts and rips on belts 78" wide.

Minimal set up saves time and Reduces service cost due to easier handling and mobility.

Minimal Voltage requirements due to optional energy adjustments. (110 and 220 V 1 PH)  
No generator needed.

Repairs on belt may not require removal of rollers or reduction of belt tension.

*Talk to  
one of our  
fully trained  
representatives*



**INDUSTRIAL  
RUBBER  
PRODUCTS LTD.**

A member of the  
IRP Group of Companies

**INDUSTRIAL RUBBER PRODUCTS LTD.**

Address: 4B Gaston Street, Chaguanas, Trinidad, W.I.

Phone: (868) 674-0693 / 0694 / 3632 Fax: (868) 665-1310 / 665-7728

Email: [sales.industrial@irpltd.com](mailto:sales.industrial@irpltd.com) / [csr.ind@irpltd.com](mailto:csr.ind@irpltd.com)

Website: [www.irpltd.com](http://www.irpltd.com)